Amendments to the Specification - Page 11

Immediately after the paragraph which begins on line 1 and ends on line 10 of page 11 in the specification as originally filed, please add the following new paragraph:

Focusing for a moment on a feature of the invention mentioned earlier, and seen especially well with reference to Figs. 2, 3 and 5, the "continuum" bridging of grout which extends through opening, or passage, 12b in the base of column 12 provides an important vertical lock against upward movement of the column. As can be seen, the lower extremity of this grout continuum furnishes what may be thought of as vertical abutment engagement, blockage and interference against column lifting by virtue of the fact that it directly overlies the upwardly facing lower perimetral edge of passage 12b (see especially Fig. 2). A "facial" view of this lower edge of passage 12b is seen exposed (i.e. without grout yet engaging it) in Fig. 5. It is this "lower edge" vertical abutment engagement condition which produces the important lock against vertical, upward column movement of column 12 out of the bucket-well of the invention.